

FIG. 1




FIG. 3




FIG. 2





FIG. 4



20240701 14:07:04

FIG. 5




FIG. 6




FIG. 7




FIG. 12

NORMAL
RUNNING




FIG. 8




FIG. 9




FIG. 9

FIG. 10




FIG. 11




FIG. 13

TORQUE ASSIST / REGENERATION




FIG. 14

ENGINE START / IDLE CHARGE




FIG. 15




FIG. 16




FIG. 16

FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26





FIG. 27



00000000 00000000

FIG. 28




FIG. 29

